

CERTIFICATE

This is to certify that I have inspected the Building of Chaudhari central convent school at survey no- 948,949,950,951, Gwalior Road, Bhind, The building at Ground floor (built up area 1248.0 sqm)) has been completed and building fit for use of institutional purpose.

This is for your kind need full.

Date - 28/02/2017

Place - Gwalior

Grunde

SUB-ENGINEER P.W.D. Sub . v sion No. 1

BHIND (M.P.)

मुख्य नमर पालिका अधिकारी जार पालिका विषय (म.प.)

AJAY KATAFIA COUNCIL DE ARCHETETT